

## Waste Site Reclassification Form

<b>Date Submitted:</b> 02/11/2008  <b>Originator:</b> Greg Berlin  <b>Phone:</b> 376-2389	<b>Operable Units:</b> 200-SW-1  <b>Waste Site ID:</b> 200-W-35  <b>Type of Reclassification Action:</b> Closed Out: <input type="checkbox"/> Interim Closed Out: <input type="checkbox"/> No Action: <input type="checkbox"/> RCRA Postclosure: <input type="checkbox"/> Rejected: <input checked="" type="checkbox"/> Consolidated: <input type="checkbox"/>	<b>Control Number:</b> 2008-012
---	---	---------------------------------



This form documents agreement among parties listed authorizing classification of the subject unit as Closed Out, Interim Closed Out, No Action, RCRA Postclosure, Rejected, or Consolidated. This form also authorizes backfill of the waste management unit, if appropriate, for Closed Out and Interim Closed out units. Final removal from the NPL of No Action and Closed Out waste management units will occur at a future date.

**Description of Current Waste Site Conditions:**  
 (Summarize status of investigation/remediation of the waste sites.)  
 This area was used for various technology development tests during the late 1970's and early 1980's. A site visit in 1995 identified some aluminum pipes laying around the area identified as subsite 200-W-35A. It was used as an Infiltration Test Site to determine the infiltration capacity of new cribs prior to their construction. Subsite 200-W-35B consisted of a pit with a plywood cover and a circular hole cut in the plywood. It was used to develop a tool to sample the 241-Z-361 Tank. Three drums were welded together and filled with a thick bentonite slurry and food coloring to simulate the contents of the 241-Z-361 Tank. It was documented that no hazardous or radioactive materials were used in any of the tests. Subsites B and C were backfilled with clean dirt on June 20, 1997.

**Basis for Reclassification:**  
 (For closeout, reference supporting documentation, as listed in Table 3.)  
 The open pit (subsite 200-W-35 B) and the buried garbage can (subsite 200-W-35 C) were backfilled with clean dirt on June 20, 1997 to eliminate physical safety hazards. No hazardous or radioactive constituents were used in any of the tests conducted in this area.

This site was originally reclassified to "No Action" on 5/6/2004. It is requested that the reclassification status be re-evaluated to a status of "Rejected". The Rejected status will preclude carrying the site forward through the CERCLA process.

**Waste Site Controls**  
 Engineered Controls: Yes ☐ No ☒      Institutional Controls: Yes ☐ No ☒      O&M requirements: Yes ☐ No ☒  
 If any of the Waste Site Controls are checked Yes specify control requirements including reference to the Record of Decision, TSD Closure Letter, or other relevant documents.  
 None required.

<b>Briant Charboneau</b> DOE Project Manager	 Signature	4-29-2008 Date
<b>John B. Price</b> Ecology Project Manager	 Signature	5-13-2008 Date
EPA Project Manager	Signature	Date

RECEIVED

MAY 29 2008

EDMC